

Service & Parts Information

Product Improvement Information

CLAAS Omaha
Technical Support,

MB

Version 1




CLAAS LEXION 780 - 730

Improvement Kit: Rotor Flaps — Valve

Type of info: General
Group: 42
CLAAS No.: 13575

NOTE: Service Information Bulletins **Do Not** Constitute warranty authorization to update units. This Service Information is for informational purposes only.

INFORMATION: On CLAAS LEXION machines there is a Improvement kit that will operate the 3rd and 4th rotor flaps individually which will improve the threshing function of the machine during harvesting.



Improvement kit **00 1826 651.0** can be ordered through the CLAAS Parts Department in Columbus Indiana.

The assembly instructions **00 288 880.1** can be downloaded from WebTIC.

The Installation will take approx. 4.00 hours. This is for informational purposes only.

SERVICE & PARTS